

## Windows Workshop 6/18/10

### Recommended Tools & Materials

1. Razor blade scraper
2. Linoleum knife
3. Putty knives – 1¼" to 1½", stiff & flexible
4. Blades – narrow & wide, very stiff. Used for prying molding up w/o damaging
5. Paint scrapers – Red Devil, 1" & 2"
6. 2-handed paint scraper
7. Pry bar – small
8. Heat gun – 2 temps (low & high) Max 1000F on high
9. Drill w/ wire brushes (for cleaning hardware)
10. Paint pot & pot hook
11. Various clamps – bar, pipe, C
12. Shop Vacuum (6 gal max)
13. Drop cloths
14. Dust mask or respirator
15. Caulk gun & acrylic latex caulk
16. Masking tape
17. Duct tape
18. Ziploc bags (for labeling hardware, screws, etc.)
19. Gorilla glue (small)
20. Wood glue - Titebond
21. Sanding blocks – 3M 2¾" x 5"
22. Sandpaper – Klingspor 80 grit
23. Rotary & belt sanders
24. Brass springsteel weatherstripping
25. Glazing compound – DAP
26. Pushpoints – CRL, Binswanger